

SMSC Service Sheet

Sand Mountain Shooter's Club

626 Bloodworth Rd. Boaz, AL 35956

Ph. (256) 593-8027 Fax (256) 593-8587

<p>Minimum Service Charge \$25.00</p>	<p>Cost Estimates \$10.00 (disassemble, inspect, advice & re-assemble only) FREE ADVICE \$5.00</p>	<p>Written Appraisals \$25.00 & up</p>
<p>Clean & Lube \$25.00 & up (includes complete stripping of gun, cleaning & lubricating all parts, re-assemble, & testing for proper function.)</p>	<p>Mount Scope \$40.00 & up (includes mounting, checking scope, & zeroing in.) (Does not include ammo)</p>	<p>Re-Mount Scope \$40.00 & up (If someone else already HACKED it up, and you want us to take it apart and re-do it the right way.)</p>
<p>Sight in customers guns \$20.00 (per gun) (does not include ammo)</p>	<p>Pattern Shotgun \$25.00 & up (Does not include ammo, targets, etc..)</p>	<p>Drill & Tap barrel or receiver for sights \$10.00 & up per hole (Off Season Only!) (Plus \$25.00 set up fee)</p>
<p>Revolver Action Job \$45.00 & up (includes clean & smoothing of action, does not include replacement of parts.)</p>	<p>Semi-Auto Pistol Action Job \$45.00 & up (includes cleaning & smoothing of action, does not include any parts.)</p>	<p>Throat, Polish Barrel & Feed Ramp of 1911 Auto \$40.00 & up</p>
<p>Fit New Trigger to 1911 \$25.00 & up (does not include cost of trigger)</p>	<p>Fit New Hammer to 1911 \$25.00 & up (does not include cost of hammer)</p>	<p>Modify 1911 Auto Frame For Beavertail Safety \$40.00 & up (includes fitting of safety, does not include cost of safety or refinishing)</p>
	<p>Rush Jobs Regular charges--Plus Whatever I want to charge for the Extra Service</p>	